



Rm. 408, Building 1, No. 31, Yinshan Road
Yuelu District, Changsha, Hunan 410013
People's Republic of China

Tel: +86-13636523212
Email: sales@aemproduct.com
Web: www.aemproduct.com

Current Version: 1.0
Revision Date: Nov 14, 2014

Material Safety Data Sheet

Identity: Nickel Sputtering Target

Formula: Ni

SECTION I - GENERAL INFORMATION

Manufacturer: Advanced Engineering Materials Limited (AEM)

The information below is believed to be accurate and represents the best information available to AEM. However, AEM makes no warranty, expressed or implied with respect to such information and assumes no liability resulting from its use.

SECTION II – INGREDIENTS/SUMMARY OF HAZARDS

Molecular Weight: 58.69

CAS #	%	OSHA/PEL	ACGIH TLV
7440-02-0	0.0-100.0	1.0 mg/m ³	1.0 mg/m ³

SECTION III – PHYSICAL DATA

Physical State: Solid

Boiling Point: 2730.00°C	Specific Gravity (H ₂ O=1): 8.90
Melting Point: 1455.00°C	Vapor Pressure (vs. air or mmHg): 1mm at 1810.0°C
Evaporation Rate: N/A	Vapor Density (vs. air=1): N/A
Solubility in water: Insoluble	Percent Volatile: N/A

Appearance and Odor: Silvery-white, metallic powder, odorless

SECTION IV – FIRE AND EXPLOSION HAZARD DATA

Flash Point: N/A *Explosive Limits:* LEL: N/A UEL: N/A

Method Used: Flammable Solid

Extinguishing Media:

Use Class D or other suitable extinguishing agent for metal fires

Special Fire Fighting Procedures:

Firefighters must wear full face, self-contained breathing apparatus with full protective clothing to prevent contact with skin and eyes. Fumes from fire are hazardous. Isolate runoff to prevent environmental pollution.

Unusual Fire and Explosion Hazards:



Rm. 408, Building 1, No. 31, Yinshan Road
Yuelu District, Changsha, Hunan 410013
People's Republic of China

Tel: +86-13636523212
Email: sales@aemproduct.com
Web: www.aemproduct.com

Contact with strong acids may form flammable and explosive hydrogen gas. Contact with sulfur may cause evolution of heat. Nickel reacts violently with fluorine, ammonium nitrate, hydrazine, ammonia, (H₂ + dioxane), per formic acid, phosphorous, selenium, sulfur and (Ti + KClO₃)

SECTION V – HEALTH HAZARDS

Routes of entry:

Inhalation? Yes Skin? Yes Eyes? Yes Ingestion? Yes Other? No

Signs and Symptoms of Exposure:

Inhalation: May cause a red, dry, sore nose and throat, coughing and shortness of breath

Ingestion: May cause gastritis, convulsions, asphyxia, giddiness, nausea, diarrhea and vomiting.

Nervous symptoms include tremors, chorea-like movements and paralysis

Skin: May cause redness, itching, swelling, burning and ulcers

Eye: May cause redness, itching, and watering

Health Hazards (Acute and Chronic):

Nickel is a confirmed carcinogen with experimental carcinogenic, neoplastigenic, tumorigenic and teratogenic data. Poison by ingestion, intratracheal, intraperitoneal, subcutaneous and intravenous routes. An experimental teratogen. Ingestion of soluble salts causes nausea, vomiting, and diarrhea. Hypersensitivity to nickel is common and can cause allergic contact dermatitis, pulmonary asthma, conjunctivitis and inflammatory reactions around nickel containing medical implants and prosthesis. (Sax, Dangerous Properties of Industrial Materials, eighth edition)

Inhalation:

Acute: May cause irritation to the upper respiratory tract, mucous membranes and nasal cavities. May cause pulmonary asthma attacks, metal fume fever and non-infectious pneumonia

Chronic: Prolonged or repeated inhalation may cause pneumonitis

Ingestion:

Acute: Nickel is poison by ingestion. Large doses may cause intestinal disorders, convulsions and asphyxia

Chronic: May cause Nickel toxicity

Skin:

Acute: May cause irritation

Chronic: May sensitize with skin, cause allergic dermatitis, eczematous dermatitis and may be accompanied a week later with superficial skin ulcers, which may discharge and become crusted

Eye:

Acute: May cause irritation

Chronic: May cause conjunctivitis

Target Organs: Nasal cavities, respiratory system, lungs, blood, mucous membranes, gastrointestinal



Advanced Engineering Materials

Rm. 408, Building 1, No. 31, Yinshan Road
Yuelu District, Changsha, Hunan 410013
People's Republic of China

Tel: +86-13636523212
Email: sales@aemproduct.com
Web: www.aemproduct.com

system, eyes and skin.

Carcinogenicity: NTP? Yes
Yes

IARC Monographs? Yes

OSHA Regulated?

Medical Conditions Aggravated by Exposure:

Pre-existing respiratory disorders, pulmonary functions, asthma, and skin disorder



Rm. 408, Building 1, No. 31, Yinshan Road
Yuelu District, Changsha, Hunan 410013
People's Republic of China

Tel: +86-13636523212
Email: sales@aemproduct.com
Web: www.aemproduct.com

Emergency and First Aid Procedures:

- Inhalation:* Remove victim to fresh air, keep warm and quiet, and give oxygen if breathing is difficult; seek medical attention
- Ingestion:* Give 1-2 glasses of milk or water and induce vomiting, seek medical attention. Never induce vomiting or give anything by mouth to an unconscious person
- Skin:* Remove contaminated clothing, brush material off skin, wash affected area with mild soap and water, and seek medical attention if symptoms persist
- Eye:* Flush eyes with lukewarm water, lifting upper and lower eyelids for at least 15 minutes and seek medical attention

SECTION VI - REACTIVITY DATA

Stability: Stable

Conditions to Avoid (stability): None

Incompatibility:

Oxidizing agents, sulfur compounds, hydrogen oxygen, magnesium silicate, methanol, organic solvents, aluminum, aluminum chloride, ethylene, p-dioxan, strong acids, fluorine, ammonium nitrate, per formic acid, selenium, ammonia, hydrazine, phosphorous, titanium chlorate, potassium chlorate, wood and other combustibles

Hazardous Decomposition or Byproducts: Nickel carbonyl, oxides of nitrogen, hydrogen gas

Hazardous Polymerization: Will not occur

Conditions to avoid (hazardous polymerization): None

SECTION VII - PRECAUTIONS FOR SAFE HANDLING AND USE

Precautions to be taken in handling:

Store and handle in a controlled environment under and inert gas such as Argon (Ar)

Steps to be taken in case material is released or spilled:

Wear appropriate respiratory and protective equipment specified in section VIII. Isolate spill area, provide ventilation and extinguish sources of ignition. Vacuum up spill using a high efficiency particulate absolute (HEPA) air filter and place in a closed container for proper disposal. Take care not to raise dust. Use non-sparking tools

Waste disposal method:

Dispose of in accordance with state, local, and federal regulations.

Hazard Label Information:

Store in cool, dry area and in tightly sealed container. Wash thoroughly after handling.



Rm. 408, Building 1, No. 31, Yinshan Road
Yuelu District, Changsha, Hunan 410013
People's Republic of China

Tel: +86-13636523212
Email: sales@aemproduct.com
Web: www.aemproduct.com

SECTION VIII - CONTROL MEASURES

Protective Equipment Summary (Hazard Label Information):

NIOSH approved respirator, impervious gloves, safety glasses, clothes to prevent skin contact.

Ventilation:

Local Exhaust: To maintain concentration at low exposure levels. Mechanical (General):

NOT Recommended.

Other: Handle in a controlled environment in an inert gas such as Argon (Ar)

Work/Hygienic/Maintenance Practices:

Implement engineering and work practice controls to reduce and maintain concentration of exposure at low levels. Use good housekeeping and sanitation practices. Do not use tobacco or food in work area.

Wash thoroughly before eating or smoking. Do not blow dust off clothing or skin with compressed air.

Please be advised that N/A can either mean Not Applicable or No Data Has Been Established
